


Sidewalk Ramps


Ellis Burge and Kevin Vrchoticky





www.Cedar-Rapids.org






www.Cedar-Rapids.org




Ramp Alignment






Curb Cut






Checking Formwork





Turning Space

Max slope in ANY direction is 2.0%






Ramp Running Slope

Target: 6.25%

Max: 8.33%






Ramp Cross Slope

Target 1.5%


Max Slope: 2%





Secondary Ramp

Continuous run over 8.3% must be longer then 15'
Cross slope max: 2.0%
Transition panel is located after the secondary ramp





Questions?