ATTACHMENT E

ENVIRONMENTAL TESTING LABORATORIES, INC
38900 Huron River Drive
Romulus, Michigan 48174
(734) 955-6600
Fax: (734) 992-2261
www.2etl.com

Bulk Asbestos Chain of Custody

ETL Project #: 180649

Client:	Hawkeye Environmental	Contact:	Project Location/name: Ushers Ferry
		Phone: 319-333-7420	
Address:	814 Wood Lily Road Solon, IA 52333	Fax:	
		E-mail: Steve@HawkeyeEnv.com	Client Project #:
Please Provide Results: ☐ Email ☐ Fax ☐ Verbal ☐ Other _____			Date Sampled: 6-8-16

Turnaround Time (TAT): ☐ RUSH ☐ Same Day ☐ 24 hr ☐ 48 hr ☒ Standard (3+ days) ☐ Other _____

PLM Instructions
(Check all that apply)

☒ PLM EPA600/R-93/116, 1993 (Standard method)	☐ Stop at 1st Positive - *Clearly mark Homogenous Group*
☐ Point Counting: 400 Points*	
☐ PLM Non-Building Material (Dust, Wipe, Tape)	☐ Soil or Vermiculite Analysis *

** Additional charge and turnaround may be required*

Lab ID	Sample ID	Sample Location	Material Description
424618	1	Chimney	PLASTER
424619	2	upper window	glaze
424620	3	upper bedroom	DRYWALL
424621	4	ceiling	DRYWALL
424622	5	Window upper	glaze
424623	6	Roof	shingle
424624	7	Downstair Room	PLASTER
424625	8	Attic	insulation
424626	9	Bathroom	12X12 green tile
424627	10	Bathroom	yellow glue
424628	11	handing to bacement	9X9 gray tile
424629	12	handing to bacement	MASTIC

			Date	Time
Relinquished (Name/Organization):	Michael Johnson		6-8-16	4 PM
Received (Name/ETL):		L.P.	6/9/16	am/p
Stereoscopical Analysis (Name/ETL):		lm	6-10-16	am/p
Sample Login (Name/ETL):		L.P.	6/9/16	am/p
Analysis (Name/ETL):		lm	6-10-16	am/p
QA/QC Review (Name/ETL):				am/p

Special Instructions:

Remarks

ENVIRONMENTAL TESTING LABORATORIES, INC
38900 HURON RIVER DRIVE
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 992-2261
www.2etl.com

Bulk Asbestos Chain of Custody

ETL Project #: 180649

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Lab ID	Sample ID	Sample Location	Material Description
424630	13	Basement Boiler	paper
424631	14	Basement Boiler	paper
424632	15	Front Room	ceiling plaster
424633	16	Lower Window	glaze
424634	17	Chimney	tar