



Sidewalk Grinding Project Inspections Completed 11/01/2015 - 10/31/2016

Work Order Nbr	Address	GPN	Notes	Length	
1	SWI-05-2015-004251	4124 LARK CT NE	140820101201000	6 panels east of turning panel for one and north edge of drive for other 8'.	8
2	SWI-05-2015-004300	4051 42ND ST NE	140710100100000	2 grinds on 42nd. 2 grinds on 42nd, 8'	8
3	SWI-05-2015-004307	2513 42ND ST NE	140810200300000	R1: West side of driveway. R2: East side of driveway.	8
4	SWI-05-2015-004352	4131 WEDGEWOOD DR NE	140812900100000	4.5 panels from the fence line on 42nd	4
5	SWI-05-2015-004402	4413 ADAMS CT NE	140623100300000	on edge of driveway	4
6	SWI-05-2015-004405	4425 ADAMS CT NE	140623100500000	On edge of driveway	4
7	SWI-05-2015-004420	4500 ADAMS CT NE	113135101600000	6.5 panels east of driveway	4
8	SWI-05-2015-004549	2515 AMBER DR NE	140817900200000	R1: On east property line. R2: 2 panels east of driveway.	8
9	SWI-05-2015-004604	3915 BELDEN CT NE	140825300401000	4' grind south of Drive way	4
10	SWI-05-2015-004605	3905 BELDEN CT NE	140825300501000	Left edge of driveway	4
11	SWI-05-2015-004634	2050 BIRCHWOOD DR NE	140928301800000	12'. About 8 joints right of driveway are 2 grinds. Then 1 more.	12
12	SWI-05-2015-004635	2058 BIRCHWOOD DR NE	140928301700000	12'. 1 at expansion, 1 near driveway...	12
13	SWI-05-2015-004637	2110 BIRCHWOOD DR NE	140928301500000	4'. Between new and old conc.	4
14	SWI-05-2015-004652	2023 BIRCHWOOD DR NE	140928400200000	4'. Between new and old conc.	4
15	SWI-05-2015-004691	2131 BIRCHWOOD DR NE	140928401000000	12'. 2 of them appear to be between new and old conc.	12
16	SWI-05-2015-004724	4020 BLUE JAY DR NE	140820104000000	R1: 10 panels south of driveway	4
17	SWI-05-2015-004730	4131 BLUE JAY DR NE	140822602301000	4'. 1 joint right of driveway	4
18	SWI-05-2015-004806	5602 BLACK OAK DR NE	130140300800000	R1: 3 panels west of driveway	4
19	SWI-05-2015-004834	5512 BLACK OAK DR NE	130140300600000	Left edge of driveway	4
20	SWI-05-2015-004969	2612 BROOKLAND DR NE	140810601300000	4 panels East of drive way, 1 on E side of driveway. 1 panel west of riveway. 3 panels W of driveway on the East side of the Drive way 1 panel west of drive way 3 panels west of drive way	16
21	SWI-05-2015-004974	2524 BROOKLAND DR NE	140810601800000	4 panels east of the Drive Way	4
22	SWI-05-2015-004978	2533 BROOKLAND DR NE	140817800100000	4 panels from intersection panel and 5 panels from driveway. E-W side.	8
23	SWI-05-2015-005058	3810 CEDAR BLUFF CT NE	131220104300000	One grind at south end of property line.	4
24	SWI-05-2015-005066	2034 CAROLINA DR NE	140927902600000	1 panel E of driveway	4
25	SWI-05-2015-005067	2066 CAROLINA DR NE	140927902200000	Perhaps by tree in center of lot.	4
26	SWI-05-2015-005068	2074 CAROLINA DR NE	140927902100000	6 spots to grind down	24
27	SWI-05-2015-005069	2100 CAROLINA DR NE	140927902000000	15' east of driveway	4
28	SWI-05-2015-005098	2058 CAROLINA DR NE	140927902300000	between new and old concrete	4
29	SWI-05-2015-005099	2050 CAROLINA DR NE	140927902400000	10 panels E of driveway (2 joints there)	8
30	SWI-05-2015-005139	4012 CEDAR BLUFF CT NE	131220103100000	The grind is on the right side of the property line.	4
31	SWI-05-2015-005142	3826 CEDAR BLUFF CT NE	131220103600000	Grind is 2 panels right of drive way.	4
32	SWI-05-2015-005180	6715 CEDAR VIEW CT NE	131220103800000	one is 2 panels right of drive way, and one grind is 1 panel right of the drive way. one grind is on left of drive way, and one is nine panels left of drive way.	16
33	SWI-05-2015-005306	2906 CHIPPEWA TRL NE	131237800300000	R1: on north property line	4
34	SWI-05-2015-005309	6725 CHOCTAW RIDGE RD NE	131235101400000	R1: 4 panels left of driveway	4

	Work Order Nbr	Address	GPN	Notes	Length
35	SWI-05-2015-005311	6817 CHOCTAW RIDGE RD NE	131235300100000	R1: Edge of driveway	4
36	SWI-05-2015-005312	6829 CHOCTAW RIDGE RD NE	131235300200000	R1: on edge of driveway	4
37	SWI-05-2015-005329	4502 CHESTNUT RIDGE RD NE	140637602600000	R1: 2 panels to the right of driveway	4
38	SWI-05-2015-005331	4510 CHESTNUT RIDGE RD NE	140630201400000	R1: 6 panels right of driveway. R2: 11 panels left of driveway.	8
39	SWI-05-2015-005433	4702 CHESTNUT RIDGE RD NE	140630202200000	R1: on edge of driveway	4
40	SWI-05-2015-005443	4711 CHESTNUT RIDGE RD NE	140630300600000	R1: 9 panels right of driveway	4
41	SWI-05-2015-005445	5015 CHESTNUT RIDGE RD NE	140630301100000	R1: On edge of driveway	4
42	SWI-05-2015-005449	4600 CHESTNUT RIDGE RD NE	140630201700000	R1: on edge of walkway up to house	4
43	SWI-05-2015-005463	6707 DEER HORN TR NE	131238000100000	R1: 6 panels north of driveway	4
44	SWI-05-2015-005467	6704 KIOWA TRACE NE	131320300400000	R1: 4 panels north of driveway. R2: 6 panels north of driveway.	8
	SWI-05-2015-005475	6614 CHOCTAW RIDGE RD NE	131237700200000	R1: On right property line. R2: 5 panels to right of driveway.	8
45					
46	SWI-05-2015-005546	4541 COVENTRY LN NE	140545400100000	R1: 3 panels right of R2. R2: 3 panels Right of driveway.	8
47	SWI-05-2015-005549	4625 COVENTRY LN NE	140543000500000	R1: Near city tree	4
48	SWI-05-2015-005552	4715 COVENTRY LN NE	140543000200000	R1: Next to city tree	4
49	SWI-05-2015-005555	3625 COPPERMILL RD NE	140827602700000	One 4 panels east of drive Way, and another 5 panels west of drive way.	8
50	SWI-05-2015-005572	3620 COPPERMILL RD NE	140828000500000	Grind is to the left of the drive way.	4
51	SWI-05-2015-005588	3705 COPPERMILL RD NE	140827603000000	one of the grinds is 3 panels north of drive way	8
52	SWI-05-2015-005592	6520 COTTAGE HILL LN NE	131227600300000	1) 2 joints from the whiter conc.	4
53	SWI-05-2015-005596	6606 COTTAGE HILL LN NE	131227600400000	Old conc meets newer conc.	4
54	SWI-05-2015-005613	4500 COVENTRY LN NE	140545200700000	By brand new tree next to driveway.	4
55	SWI-05-2015-005617	4530 COVENTRY LN NE	140545300200000	Grinds left of driveway	12
56	SWI-05-2015-005623	4301 WESTCHESTER DR NE	140545400900000	4' in the low spot perhaps on Coventry side	4
57	SWI-05-2015-005628	6824 DEER HORN TRL NE	131235100500000	R1: On east property line	4
58	SWI-05-2015-005687	3801 DOVE CT NE	140820109300000	either at drive or 3 panels right of driveway	4
59	SWI-05-2015-005690	3821 DOVE CT NE	140820109400000	LT of driveway where new conc meets old conc	4
60	SWI-05-2015-005695	3900 DOVE CT NE	140820109900000	4' in driveway near LT side. 4' 4 joints from LT edge of drive	12
61	SWI-05-2015-005827	2525 FALCON DR NE	140810600400000	approx 9 or so panels left of driveway.	4
62	SWI-05-2015-005828	2517 FALCON DR NE	140810600300000	2 grinds. On at each edge of driveway	8
63	SWI-05-2015-005829	2509 FALCON DR NE	140810600200000	3 joints LT of driveway	4
64	SWI-05-2015-005841	4103 FALBROOK DR NE	140812701800000	LT side of driveway	4
65	SWI-05-2015-005877	2810 FALCON DR NE	140813101100000	RT side of driveway	4
66	SWI-05-2015-005940	5032 ERIN CT NE	140720201800000	The grind is on Property line left of house.	4
67	SWI-05-2015-005996	2604 FALBROOK DR NE	140810201100000	RT side of driveway ?	4
68	SWI-05-2015-005998	2500 FALBROOK DR NE	140810201600000	2 joints RT of the driveway	4
69	SWI-05-2015-006004	4115 FALBROOK DR NE	140812700100000	R1 - On north side of driveway. R2 - 3 panels south of the turning panel.	8
70	SWI-05-2015-006011	3343 FALCON DR NE	140820107400000	LT edge of driveway	4
71	SWI-05-2015-006012	3327 FALCON DR NE	140820107500000	2 joints RT of the driveway	4
72	SWI-05-2015-006020	3350 FALCON DR NE	140820200500000	RT side of driveway	4
73	SWI-05-2015-006030	4101 FOREST VIEW CT NE	140722602400000	R1: on edge of driveway	4
74	SWI-05-2015-006046	2541 FALCON DR NE	140810600600000	5 panels LT of driveway	4
75	SWI-05-2015-006073	4102 FOREST VIEW CT NE	140722600600000	2 panels to the right of Drive Way.	4

	Work Order Nbr	Address	GPN	Notes	Length
76	SWI-05-2015-006088	6121 FOREST MEADOW CT NE	131242901400000	R1: on right edge of driveway	4
77	SWI-05-2015-006096	2821 FALCON DR NE	140813200300000	Far LT side of prop	4
78	SWI-05-2015-006102	3119 FALCON CT NE	140813201400000	4' curb grind where sidewalk meets street and 4' sidewalk grind about 6' away from the street Contractor to receive double unit cost for curb grind	12
79	SWI-05-2015-006143	3906 FOREST VIEW CT NE	140722601300000	On edge of property	4
80	SWI-05-2015-006144	3900 FOREST VIEW CT NE	140722601400000	On edge of property	4
81	SWI-05-2015-006147	3915 FOREST VIEW CT NE	140722601700000	9 panels to the right of the drive way.	4
82	SWI-05-2015-006189	2520 GLASS RD NE	140818000800000	R1: by driveway, R2: 3 panels east of driveway	8
83	SWI-05-2015-006232	2810 GLEN ELM DR NE	140812701100000	mid driveway	4
84	SWI-05-2015-006242	5910 SPRING VIEW CT NE	113135102600000	R1: On backyard sidewalk 2 panels from storm drain	4
85	SWI-05-2015-006270	3748 OLD ORCHARD RD NE	140827601400000	10 panels N of prop line. 1 panel S of driveway. 10 panels S of driveway. ON Glass side, 8 panels from turning panel.	16
86	SWI-05-2015-006283	2407 GLASS RD NE	140840100200000	2. 1 at each edge of driveway.	8
87	SWI-05-2015-006301	6008 GIBSON DR NE	113135201000000	R1: 5 Panels south of driveway	4
88	SWI-05-2015-006335	5808 SPRING VIEW CT NE	113135103100000	R1: on backyard property line between 5808 & 5814	4
89	SWI-05-2015-006357	2570 GLASS RD NE	140817800900000	Location: 10 panels west of driveway.	4
90	SWI-05-2015-006370	3501 LOCHWOOD DR NE	140818101200000	R1 - 9 panels from fire hydrant on Glass Rd R2 - 2 panels from fire hydrant on Glass Rd See notes and attachments of sidewalk segment on Lochwood Dr NE for 3510.	8
91	SWI-05-2015-006420	2612 GLEN ELM DR NE	140810401300000	R1 RT edge of drive. R2 is LT edge of drive R3 is 19.5' LT of drive. 12'.	4
92	SWI-05-2015-006421	2604 GLEN ELM DR NE	140810401400000	RT edge of drive. LT edge of Drive. R3 looks to be 1 or 2 panels farther LT of R2.	12
93	SWI-05-2015-006433	2815 GLEN ELM DR NE	140813100300000	Far LT side near mud-jack	4
94	SWI-05-2015-006444	4004 HARWOOD DR NE	140720101000000	R1: 1 panel right of driveway	4
95	SWI-05-2015-006467	4102 HARWOOD DR NE	140720100500000	R1: left edge of driveway. R2: 3 panels right of driveway	8
96	SWI-05-2015-006468	4028 HARWOOD DR NE	140720100600000	R1: right edge of driveway	4
97	SWI-05-2015-006469	4022 HARWOOD DR NE	140720100700000	R1: left edge of driveway, R2: 1 panel right of driveway	8
98	SWI-05-2015-006473	3519 HEATHERIDGE DR NE	140815201400000	LT edge of driveway	4
99	SWI-05-2015-006474	3515 HEATHERIDGE DR NE	140815201300000	1.5 panels RT of driveway also 2 panels LT of driveway	8
100	SWI-05-2015-006475	3514 HEATHERIDGE DR NE	140815201000000	1 grind is by light post, the other is two panels left of the drive way, and the other is in the drive way. 3rd repair is in driveway.	12
101	SWI-05-2015-006531	3609 HEATHERIDGE DR NE	140815202000000	RT side of driveway. Second is 2 panels more right w/ the water service	8
102	SWI-05-2015-006602	4705 LANCASTER DR NE	140542901600000	R1: 5 panels right of driveway.	4
103	SWI-05-2015-006604	4635 LANCASTER DR NE	140542901500000	Cracked panel @ drive edge	4
104	SWI-05-2015-006608	4545 LANCASTER DR NE	140542901100000	R1: by city tree. R2: In driveway	8
105	SWI-05-2015-006614	2108 LARRY DR NE	140927700900000	1 panel RT of new 2 panel repair. Also, 1/2 panel LT of driveway.	8
106	SWI-05-2015-006633	6724 KIOWA TRCE NE	131320300300000	R1: on east property line	4
107	SWI-05-2015-006640	2034 KNOLLSHIRE RD NE	140928102200000	RT edge of drive.	4
108	SWI-05-2015-006643	2141 LARRY DR NE	140927901300000	3 panels LT of drive and RT side of drive	8
109	SWI-05-2015-006646	2117 LARRY DR NE	140927901000000	center of drive	4
110	SWI-05-2015-006657	4700 LANCASTER DR NE	140542800500000	By Tree	4
111	SWI-05-2015-006670	6617 KIOWA TRCE NE	131320400200000	R1: 3 panels left of driveway. R2: at LT side of driveway	

	Work Order Nbr	Address	GPN	Notes	Length
112	SWI-05-2015-006677	6704 KIOWA TRCE NE	131320300400000	R1: 4 panels N of drive. R2: 6 panels N of drive. R3: 3 panels west of turning panel.	
113	SWI-05-2015-006681	6607 KIOWA TRCE NE	131320400100000	Near city tree	8
114	SWI-05-2015-006684	7015 KIOWA TRACE NE	131322700900000	R1: On edge of driveway	4
115	SWI-05-2015-006687	7012 KIOWA TRACE NE	131322600800000	R1: on edge of driveway	4
	SWI-05-2015-006704	2050 KNOLLSHIRE RD NE	140928102000000	R1 grind is 25' East of Drive way. R2 grind is east of Drive way. R3 grind is west of Drive way.	12
116	SWI-05-2015-006711	2059 KNOLLSHIRE RD NE	140928300600000	R1 is 15' from West of Driveway, R2 is 23'-24' East of Driveway, R3 is West of Tree	12
117	SWI-05-2015-006715	2141 KNOLLSHIRE RD NE	140928301100000	1 on N-S (painted). RT side of driveway and 1 panel LT of LT side of driveway.	12
118					
119	SWI-05-2015-006723	4544 LANCASTER DR NE	140545200200000	By driveway	4
120	SWI-05-2015-006725	4530 LANCASTER DR NE	140545200400000	Edge of driveway	4
121	SWI-05-2015-006727	4510 LANCASTER DR NE	140545200600000	By property line.	4
122	SWI-05-2015-006729	4535 LANCASTER DR NE	140545300100000	R1: By big city tree. R2: at the edge of the property line.	8
123	SWI-05-2015-006731	4126 LARK CT NE	140820101201001	1 on 42nd. 1 at N edge of driveway	4
124	SWI-05-2015-006836	3918 LEXINGTON DR NE	140822701201000	The grind is on the right edge of the Drive way.	4
125	SWI-05-2015-006868	4016 MAJESTIC CT NE	140722700700000	On property line to right of house.	4
126	SWI-05-2015-006869	4024 MAJESTIC CT NE	140722700600000	R1: on property line right of house	4
127	SWI-05-2015-006886	3549 LYNBROOK DR NE	140928001000000	3 joints RT of tree and 4 joints LT of tree	8
128	SWI-05-2015-006916	4113 MAJESTIC CT NE	140722701900000	The grind is on the edge of DW	4
129	SWI-05-2015-006920	4009 MAJESTIC CT NE	140722701500000	The grind is 1.5 panels right of the drive way	4
130	SWI-05-2015-006934	3511 LOCHWOOD DR NE	140818101000000	2 joints W and 5 joints W of driveway	8
131	SWI-05-2015-006938	3618 LYNBROOK DR NE	140928101300000	4 panels W of driveway and 8 panels W of driveway	8
132	SWI-05-2015-006972	3523 LOCHWOOD DR NE	140818100700000	The grind is west of the drive way about 2 panels down.	4
133	SWI-05-2015-007012	3709 LYNBROOK DR NE	140928000300000	1 panel RT of driveway	4
	SWI-05-2015-007021	3640 LYNBROOK DR NE	140928101100000	N-S segment. At RT edge of driveway. N-S segment, there may be one at 5 panels south of intersection panel.	8
134					
135	SWI-05-2015-007027	3919 MAJESTIC CT NE	140722701300000	about 6 panels LT of driveway?	4
136	SWI-05-2015-007167	3416 MEADOW VIEW CT NE	131232601100000	R1: 1 panel right of driveway. R2: 2 panels left of driveway.	8
	SWI-05-2015-007213	4017 NORTH WILLOWBEND RD NE	140722604600000	4 panels from the drive way.	4
137					
	SWI-05-2015-007219	4113 NORTH WILLOWBEND RD NE	140722604000000	On the edge of drive way.	4
138					
139	SWI-05-2015-007246	4811 MILLBROOK CT NE	140637800200000	R1: 3 panels to the right of driveway. R2: 1 panel to the left of driveway.	8
	SWI-05-2015-007250	4307 WOODSMILL CT NE	140637601300000	R1: 5 panels east of the west property line. R2: 5 panels from the turning panel of ramp.	8
140					
	SWI-05-2015-007251	4831 MORELLE RD NE	140637601500000	R1: on edge of driveway. R2: 6 panels left of driveway. R3: 12 panels left driveway.	12
141					
142	SWI-05-2015-007268	4223 MORELLE RD NE	140637800800000	R1: 3.5 panels left of driveway	4
	SWI-05-2015-007299	5110 NORTH RIVER BLVD NE	140627600400000	9 panels LT of driveway. Also 4 panels RT of driveway. Also, grind lip at RT side of driveway where there is a cracked panel. 12'.	8
143					

	Work Order Nbr	Address	GPN	Notes	Length
144	SWI-05-2015-007304	5005 NORTH RIVER BLVD NE	140630200200000	R1: Near tree R2: near storm drain	8
145	SWI-05-2015-007459	5309 OAK CREEK DR NE	130140200400000	R1: 4 panels east of driveway	4
146	SWI-05-2015-007460	5303 OAK CREEK DR NE	130140200300000	R1: Next to driveway	4
147	SWI-05-2015-007476	5318 OAK CREEK DR NE	130140100600000	R1: 2 panels west of driveway. R2: 5 panels east of driveway.	8
148	SWI-05-2015-007515	5317 OAK CREEK DR NE	130140200500000	R1: next to driveway. R2: 11 panels east of driveway	8
149	SWI-05-2015-007516	Property E of 5207 Oak Creek Dr NE	140633000100000	R1: 18 panels east of fire hydrant, (NOT MAPPED).	4
150	SWI-05-2015-007517	5207 OAK CREEK DR NE	140633000200000	R1: Near city tree	4
151	SWI-05-2015-007518	5324 OAK CREEK DR NE	130140100700000	R1: 1 panel west of driveway	4
152	SWI-05-2015-007523	4875 OAK GROVE CT NE	140635101700000	R1: on north property line	4
153	SWI-05-2015-007613	3748 OLD ORCHARD RD NE	140827601400000	R1: 10 panels north of property line, R2: 1 panel south of driveway R3: 10 panels south of driveway	12
154	SWI-05-2015-007666	3501 ORIOLE CT NE	140820108300000	RT side of driveway	4
155	SWI-05-2015-007671	3380 ORIOLE CT NE	140820108800000	1 Joint LT of driveway	4
156	SWI-05-2015-007708	4226 PINE VIEW DR NE	140538001300000	this is one panel south of the north property line.	4
157	SWI-05-2015-007715	4610 PINE VIEW DR NE	140530301000000	r1 is 4.5 panels North of drive way, r2 is 5.5 panels north of drive way, and r3 is 6.5 panels north of drive way.	12
158	SWI-05-2015-007767	4217 PINE VIEW DR NE	140537802200000	this is 1/2 a panel north of the drive way.	4
159	SWI-05-2015-007768	4209 PINE VIEW DR NE	140537802100000	grind is north of Drive way	4
160	SWI-05-2015-007775	4601 PINE VIEW DR NE	140530400900000	This is 5 panels south of the drive way.	4
161	SWI-05-2015-007835	4618 PINE VIEW DR NE	140530300900000	r1 is three panels north of the Drive way, and r2 six panels north of drive way.	8
162	SWI-05-2015-007880	3816 REDBUD RD NE	140920103200000	RT side of driveway	4
163	SWI-05-2015-007885	3926 REDBUD RD NE	140920102600000	about 10 joints LT of driveway	4
164	SWI-05-2015-007916	3625 REDBUD RD NE	140928102500000	RT edge of driveway	4
165	SWI-05-2015-007955	3470 RAVEN LN NE	140820106100000	Can do cracked panel on the left of the drive way	4
166	SWI-05-2015-007983	2042 BROOKLAND DR NE	140920201800000	1 joint from Street. Also farther N by expansion. N-S segment only.	8
167	SWI-05-2015-007984	3805 REDBUD RD NE	140920201900000	middle one is in driveway	12
168	SWI-05-2015-007994	3308 RESTON CT NE	140815202300000	the grind is on the west property line.	4
169	SWI-05-2015-007995	3300 RESTON CT NE	140815202400000	1 grind is a panel east of the drive way, and the other is 1 panel west of the east property line.	8
170	SWI-05-2015-007999	3311 RESTON CT NE	140815203000000	Grind is west side of the drive way, the other grind is two panels east of the drive way.	8
171	SWI-05-2015-008000	3319 RESTON CT NE	140815203100000	Two panels east of the drive way.	4
172	SWI-05-2015-008168	3404 RIVERBEND DR NE	140732600500000	Far LT end of prop	4
173	SWI-05-2015-008170	3427 RIVERBEND DR NE	140725200700000	Three panels to the right of the drive way.	4
174	SWI-05-2015-008174	3403 RIVERBEND DR NE	140732703100000	The grind is near the big light post.	4
175	SWI-05-2015-008175	3409 RIVERBEND DR NE	140732703200000	approx RT edge of property and 2 panels LT of there	8
176	SWI-05-2015-008177	3339 RIVERBEND DR NE	140732800100000	The grind is on the right edge of the drive way.	4
177	SWI-05-2015-008192	3904 SALLY DR NE	140813100700000	right next to water meter	4
178	SWI-05-2015-008219	3707 RIVERSIDE DR NE	140725203700000	R1: 3 panels to right of driveway, R2: on edge of driveway	8
179	SWI-05-2015-008222	3935 SALLY DR NE	140813002100000	R1: 4 panels S of driveway. R2: on driveway N side. R3: 10 panels S of driveway	12

	Work Order Nbr	Address	GPN	Notes	Length
180	SWI-05-2015-008228	4103 SALLY DR NE	140813000400000	R1: 8 panels left of driveway. R2: in driveway.	8
181	SWI-05-2015-008290	4111 RIVERSIDE DR NE	140722703400000	R1: 3 panels left of driveway	4
182	SWI-05-2015-008299	3726 RIVERSIDE DR NE	140725100500000	R1: 1 panel to right of driveway	4
183	SWI-05-2015-008300	3734 RIVERSIDE DR NE	140725100400000	R1: 1 panel to right of driveway	4
184	SWI-05-2015-008301	3800 RIVERSIDE DR NE	140725100300000	6 panels to right of driveway	4
185	SWI-05-2015-008304	3317 ROSEWOOD CT NE	140930201400000	The grinds are on each edge of the driveway.	8
186	SWI-05-2015-008305	3307 ROSEWOOD CT NE	140930201300000	2 grinds in center	8
187	SWI-05-2015-008338	3425 RIVERSIDE DR NE	140725200800000	Riverside DR, 1/2 way. also, 5 panels closer to the intersection by wall.	8
188	SWI-05-2015-008378	3833 RIVERSIDE DR NE	140722702300000	R1: 7 panels to right of driveway	4
189	SWI-05-2015-008395	4022 SALLY DR NE	140812900700000	about 4 panels LT of driveway	4
190	SWI-05-2015-008398	3945 SALLY DR NE	140813002200000	2, 2 panels apart, towards LT of property	8
191	SWI-05-2015-008479	3205 SILVERTHORNE RD NE	140815203700000	one of the grinds is by a city tree (1 joint LT of tree). 3 panels RT of 1st. 3rd is east Prop line?	12
192	SWI-05-2015-008482	3310 SILVERTHORNE RD NE	140815203300000	2 panels east from property line.	4
193	SWI-05-2015-008734	3330 SILVERTHORNE RD NE	140827900100000	grind is 7 panels east of turning ramp panel.	4
194	SWI-05-2015-008737	3315 SILVERTHORNE RD NE	140828000300000	4 panels west of the east property line.	4
195	SWI-05-2015-008760	4626 SUGAR PINE DR NE	140530200600000	R1: 5 panels south of driveway. Minimal.	4
196	SWI-05-2015-008761	4634 SUGAR PINE DR NE	140530200500000	R1: 1 panel south of driveway midpoint.	4
197	SWI-05-2015-008793	4509 SUGAR PINE DR NE	140537700700000	R1: grind on furthest panel east of property.	4
198	SWI-05-2015-008795	4713 SUGAR PINE DR NE	140530301800000	R1: 2 panels north of driveway, R2: 7 panels north of driveway	8
199	SWI-05-2015-008801	4625 SUGAR PINE DR NE	140530301500000	R1: 4 panels south of driveway, Can reimburse cracked panels.	4
200	SWI-05-2015-008844	5823 SPRING VIEW CT NE	113135102000000	On edge of driveway	4
201	SWI-05-2015-008847	5913 SPRING VIEW CT NE	113135102300000	On edge of driveway.	4
202	SWI-05-2015-008870	3303 TOWNE HOUSE DR NE	140530300100000	2 or 3 joints RT of tree on Sugar Pine	4
203	SWI-05-2015-008871	4609 SUGAR PINE DR NE	140530301300000	R1: 4.5 panels south of driveway, R2: 1 panel past repair 1	8
204	SWI-05-2015-008893	3812 SUMMERFIELD LN NE	140822701301003	The grind is 7 panels right of the drive way.	4
205	SWI-05-2015-008942	2527 TANAGER DR NE	140818000400000	1 by tree 3 panels LT of drive. 1 by LT edge of driveway	8
206	SWI-05-2015-008944	3437 SYCAMORE CT NE	140827601000000	R1 & R2: on both sides of driveway	8
207	SWI-05-2015-008950	3405 SYCAMORE CT NE	140827600200000	R1: east end of the property	4
208	SWI-05-2015-008965	3406 SYCAMORE CT NE	140827700700000	R1: 4 panels right of driveway. R2: 9 panels left of driveway.	8
209	SWI-05-2015-008987	3440 SYCAMORE CT NE	140827700400000	R1: edge of driveway. R2: 5 panels down from driveway. R3: edge of property line	12
210	SWI-05-2015-008989	3420 SYCAMORE CT NE	140827700600000	R1: 6 panels left of driveway. R2: 4 panels east of west property line.	8
211	SWI-05-2015-008991	3409 SYCAMORE CT NE	140827600300000	R1: 2 panels right of driveway. R2: 6 panels left driveway.	8
212	SWI-05-2015-008992	3425 SYCAMORE CT NE	140827600700000	R1: West property line. R2: 4 panels west of driveway.	8
213	SWI-05-2015-008994	3441 SYCAMORE CT NE	140827601100000	R1 & R2: On both sides of driveway. R3: 2 panels south of driveway.	12
214	SWI-05-2015-008995	3449 SYCAMORE CT NE	140827601300000	R1: 2 panels north of property line	4
215	SWI-05-2015-009006	2535 TANAGER DR NE	140818000500000	R1 - 5 panels east of driveway. R2 - on east property line.	8
216	SWI-05-2015-009037	3570 TIMBERLINE DR NE	140832600500000	7 panels south of drive way.	4
217	SWI-05-2015-009045	3304 TIMBER VALLEY CT NE	140930201900000	RT edge S drive. Toward LT side of N drive. 3 panels RT of large private tree. Not sure on the 4th.	16
218	SWI-05-2015-009046	3310 TIMBER VALLEY CT NE	140930201800000	This grind is two panels north of the drive way	4

	Work Order Nbr	Address	GPN	Notes	Length
219	SWI-05-2015-009080	3600 TIMBERLINE DR NE	140825103700000	r1 - south of the drive way r2 - 5 panels south of Drive way r3 - 2 panels south of city tree on property line between 3602 and 3600.	12
220	SWI-05-2015-009102	2632 TOWNE HOUSE DR NE	140540201100000	3 joints RT of the driveway	4
221	SWI-05-2015-009107	2532 TOWNE HOUSE DR NE	140540200600000	Perhaps 1 joint LT of where new meets old concrete On older conc.	4
222	SWI-05-2015-009114	3210 TOWNE HOUSE DR NE	140530100300000	1 joint LT of driveway	4
223	SWI-05-2015-009117	3320 TOWNE HOUSE DR NE	140530100700000	LT of drive by tree?	4
224	SWI-05-2015-009119	3300 TOWNE HOUSE DR NE	140530100500000	The grind is by a city tree.	4
225	SWI-05-2015-009151	2625 TOWNE HOUSE DR NE	140540500900000	1 at RT side of approach	8
226	SWI-05-2015-009152	2619 TOWNE HOUSE DR NE	140540500800000	edge of driveway	4
227	SWI-05-2015-009161	3311 TOWNE HOUSE DR NE	140530300200000	R1 is a panel left of the drive way. R2 is 6 panels from east prop line.	8
228	SWI-05-2015-009166	3130 TOWNE HOUSE DR NE	140542600201003	Grind is by property 3110 drive way	4
229	SWI-05-2015-009168	4730 LANCASTER DR NE	140542800200000	at corner post of fence on Towne House	4
230	SWI-05-2015-009209	4411 VIOLA ST NE	113135103700000	LT edge of prop near prop line	4
231	SWI-05-2015-009230	4015 WEDGEWOOD DR NE	140812900900000	3 panels S of driveway	4
232	SWI-05-2015-009232	4018 WEDGEWOOD DR NE	140812800600000	R1: 4 panels south of driveway. R2: 2 panels N of driveway. R3: 3 panels N of driveway	12
233	SWI-05-2015-009241	4321 TWIN PINE DR NE	140537901200000	R1: left of driveway, R2: right of driveway	8
234	SWI-05-2015-009284	6325 USHERS RIDGE DR NE	131230100400000	R1: on edge of driveway	4
235	SWI-05-2015-009297	3526 WENIG RD NE	140817601000000	grinds are 2 panels away from driveway	8
236	SWI-05-2015-009302	3816 WENIG RD NE	140810301100000	2 panels LT of driveway	4
237	SWI-05-2015-009305	3902 WENIG RD NE	140810300600000	2 panels LT of driveway	4
238	SWI-05-2015-009306	3926 WENIG RD NE	140810300300000	at LT edge of driveway. also near fence	8
239	SWI-05-2015-009354	4410 VIOLA ST NE	113132900900000	R1: on east property line.	4
240	SWI-05-2015-009356	4222 TWIN PINE DR NE	140537801700000	6 panels north of driveway	4
241	SWI-05-2015-009364	4424 TWIN PINE DR NE	140537800800000	Grind near west side of house near light pole.	4
242	SWI-05-2015-009369	4543 TWIN PINE DR NE	140530102200000	To the right of driveway.	4
243	SWI-05-2015-009378	4532 TWIN PINE DR NE	140537800200000	to the right of front tree and on far right property line. (looking at house)	12
244	SWI-05-2015-009381	4626 TWIN PINE DR NE	140530400500000	one on each side of the repair, and one on the crack.	8
245	SWI-05-2015-009383	4702 TWIN PINE DR NE	140530400300000	1 panel south of driveway.	4
246	SWI-05-2015-009401	4418 TWIN PINE DR NE	140537800900000	Grinds by west side of property near tree.	8
247	SWI-05-2015-009407	4518 TWIN PINE DR NE	140537800400000	Edge of property line and right of driveway	8
248	SWI-05-2015-009432	6319 USHERS RIDGE DR NE	131230100300000	R1: on edge of driveway	4
249	SWI-05-2015-009483	4010 WEDGEWOOD DR NE	140812800700000	1 panel South of driveway	4
250	SWI-05-2015-009510	2500 GLEN ELM DR NE	140810402000000	1 to RT of vault. Also RT side of driveway. both on Wenig side	8
251	SWI-05-2015-009533	2435 BROOKLAND DR NE	140810700400000	one on edge of driveway and 2 that are only 2 joints apart. All on Wenig side	12
252	SWI-05-2015-009565	4605 WESTCHESTER DR NE	140545200101021	2 joints LT of intake	4
253	SWI-05-2015-009567	4505 WESTCHESTER DR NE	140545200101021	See notes and attachments on long sidewalk segment of 4225 Westchester Dr NE. 16 panels south of drive way.	4
254	SWI-05-2015-009619	4116 WHITEWOOD CT NE	131220100300000	Grind is 4 panels right of the drive way	4
255	SWI-05-2015-009682	4920 WILLOWBEND RD NE 140720202900000		R1: 2 panels left of driveway	4

	Work Order Nbr	Address	GPN	Notes	Length
256	SWI-05-2015-009713	4823 WILLOWBEND RD NE	140720101700000	RT side of driveway	4
257	SWI-05-2015-009728	4829 WILLOWBEND RD NE	140720101800000	R1: on edge of driveway	4
258	SWI-05-2015-009729	4909 WILLOWBEND RD NE	140720102000000	R1: 2 panels right of driveway. R2: on edge of driveway	8
259	SWI-05-2015-009731	4921 WILLOWBEND RD NE	140720102200000	R1: on edge of the property	4
260	SWI-05-2015-009734	5037 WILLOWBEND RD NE	140720102800000	R1: on edge of property line	4
261	SWI-05-2015-009741	4817 WILLOWBEND RD NE	140720101600000	R1: on the edge of driveway	4
262	SWI-05-2015-009838	4300 WOODSMILL CT NE	140637600700000	R1: 5 panels to the left of driveway.	12
263	SWI-05-2015-009841	4350 WOODSMILL DR NE	140637600400000	R1: In middle right of driveway. R2: is 1 panel left of driveway	8
264	SWI-05-2015-009899	4307 WOODSMILL CT NE	140637601300000	R1, 5 panels E of W prop line. R2: 5 panels from turning panel. R3: 5 panels right of driveway	12
265	SWI-05-2015-009900	4801 MILLBROOK CT NE	140637800100000	R1: 5 panels left of driveway. R2: 8 panels left of driveway.	8
266	SWI-05-2015-009901	4800 MORELLE RD NE	140637802000000	R1: 5 panels from turning panel of ramp.	4
267	SWI-05-2016-052812	1021 14TH AVE SW	142946100700000	N-S, grind at the bad panel w/ writing. E-W by tree. 10'.	10
268	SWI-05-2016-052956	1007 17TH ST NE	141532901600000	all 3 by in/at driveway 15'	15
269	SWI-07-2016-000809	1530 BEVER AVE SE	142228402800000	Panels with grinds are near tree. 10'. Non routine inspection.	10
270	SWI-07-2016-000833	379 16TH ST SE OR 1558 BEVER Ave SE		About 3 or 4 panels away from ramp, E-W. 5'	5
271	SWI-09-2016-007495	2412 TERESA DR SW	143432702900000	2 grinds near tree. 8'	8
				Total:	1648